



## FIGURE 5. DOUBLE DIAGONAL STRINGING METHOD









LEFT Diagonal then pull tension on 2nd RIGHT Diagonal B) Attach clamp to 1st and 2st

clamp that was on it, then reattach clamp.






D) Continue building underover weave as you add add more strings





D) Insert 3rd LEFT Diagonal


apply tension, then attach clamp.



E) Begin to build weave when LEFT Diagonal and RIGHT Diagonals cross each other.









PAGE

FIG. 1







FIG. 2














FIG. 5B

FIG. 5A




FIG. 5C




FIG. 5D




FIG. 5E

